









R3 SA







No	L[mm]	W[mm]	H[mm]	PCS	BOX
103	1940	400	15	1	2/3
104	1940	400	15	1	2/3
201	902	430	36	1	1/3
301	850	400	15	1	2/3
302	850	400	15	1	2/3
303	850	400	15	3	1/3
401	849	60	15	1	1/3
5111	1915	438	2,5	2	2/3
601	1940	50	22	2	2/3






1








2






3





4





5




6





7



8



9



10

G1 x 38







26mm

H x 1



1915mm






A=B




$A=B \equiv 90^\circ$



11





12






13






14











15



16



17



ca.100 mm

ca.100 mm

